#### Work Order ID 83727

April-24-12 1:24:10 PM

\*83727\*

Page 1

Item ID: D350-591-311 Accept \*N900040100\* Setup Start **Revision ID:** Item Name: Heli-Access-Step, Long LH \*10\* **Start Date:** 24/04/2012 **Start Oty: 10.00 Cust Item ID: Required Date:** 08/05/2012 Req'd Qty: 10.00 **Customer:** Reference: Run Process Plan: MLJ Date: 17/04/24 Tooling: Approvals: Date: Stop QC: Date: SPC (Y/N): Date: Operation Reject Sequence ID/ Set Up/ Tool ID , Tool # Plan Reject Accept Insp. **Work Center ID** Description Qty Qty **Run Hours** Code Number Stamp Draw Nbr **Revision Nbr** D3272 Rev B 100 0.00 DOCUMENT CONTROL \*100\* DC 0.00 Memo Document Control Photocopy bluefile and type labels as per PPP D350-591-311 CHG001 110 0.00 Large Fab \*110\* Large Fab 0.00 Memo Large Fab 1-Bevel end for welding FWD ONLY 2-Weld Support using Jig DT8719, weld Fwd End Plate as per QSI 004 & Dwg A/RAluminum Rod M 119785 3-Grind End Plate flush

Ae 12.05.10

Dart Ae	rospace	<b>Ltd</b>								<b>ب</b> .
W/O:		<del></del>	WO	RK ORDER CHAN	GES					•
DATE	STEP	PRO	OCEDURE CHAI	IGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto
									·	
Part No	):	PAR #:	Fault Categ	ory:	NCF	l: Yes	No DQ	A:	Date: _	1
	R	esolution:	Disposition	:	QA:	N/C CI	osed:		Date: _	· · · · · · · · · · · · · · · · · · ·
NCR:			WORK ORDE	R NON-CONFORM	IANCE	(NCR	R)			
	Γ	Description of NC	Corrective Action Section				Verification		Approval	Approva
DATE	STEP	Section A	Initial Chief Eng	Action Description  Chief Eng		Sign & Date	Secti		Chief Eng	QC Inspecto
		·			!					
					!					
								*		
									-	
						·				

Work Orde		727	•	*837	727*							Page 2	
Item ID: Revision ID: Item Name:	D350-591-3 Heli-Access-S			Accept	*N900	<b>040</b>	100	*	Setup	Start Stop	*N: *N:	S1* S2*	
Start Date: Required Date: Reference:	24/04/2012 08/05/2012	Start Qty: 10.00 Req'd Qty: 10.00	*10* *10*	,	Cust Item I Customer:	D:							
Approvals:	Process Pla	n:	Date:	Tooling:	Da	ate:	_	j		Start	*N	R1*	
	QC:		Date:	SPC (Y/N):	Da	ate:	<del></del>			Stop	*N	R2*	
Sequence ID/ Work Center II	)	Operation Description		Set Up/ Run Hours	Tool ID	Tool #		Accept Qty	Reje Qty		Reject Number	Insp. Stamp	
120		QC9- Inspect visual per C	QSI004- Fusion Welds	0.00				-				-	,
*120* QC Quality Control		Мето	*	0.00			<b>م</b> ر -	10	Ø	r	BE	12/05/1	0
								-					
130		QC5- Inspect part comple	eteness to step on W/O	0.00				(3)					<b>.</b>
*130* QC Quality Control		Memo		0.00			(	(10)		<del></del> .		//V   12	:050
140		Chemical Conversion Co.	at per QSI005 4.1	0.00							L	_	
*140* HandFinish				0.00			. (	" [()		H	2 10	25-12	)
manur iiiisii		Memo		0.00			'						

Hand Finishing

W/O:			W(	ORK ORDER CHAN	GES	!				<b>.</b>
DATE	STEP	PRO	OCEDURE CHA	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						1				
								·		
Part No	-	PAR #:	Fault Cate	egory:	NCI	R: Yes	No DQA	\:	Date: _	
		esolution:								
NCR:			WORK ORD	ER NON-CONFORM	MANCE	(NCR	)			
DATE	STEP	Description of NC	Initial		ection B	Sign &	Verific		Approval	Approval
		Section A	Chief Eng	Action Description Chief Eng	1	Date	Section	on C	Chief Eng	QC Inspector
					1					
					r r					
					r r					
					i					
		•			,					_
					i					
		·						,	.,	
				·	,					
•					,					

April-24-12 1:24:10 PM

Revision ID:	D350-591-3			Accept	*N900	<u>040</u>	100	ገ*	Setup Sta	1.71	S1* S2*
Start Date: Required Date: Reference:	24/04/2012 08/05/2012		*1( *1(	=	Cust Item I Customer:	D:				,	
Approvals:	Process Pla	in:	Date:	Tooling:	D:	ate:	· ·		Run Sta	1/1	R1*
	QC:		Date:	SPC (Y/N):	D	ate:	<del></del>		Sto	<sup>'P</sup> *N	R2*
Sequence ID/ Work Center II	)	Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
150		QC3- Inspect Part Finish		0.00					0		1/
*150* QC Quality Control		Memo		0.00				10	B_	,	12.051/5"
180				0.00							
*180*		Large Fab						10	6		ke
Large Fab Large Fab		Memo 1-Assemble l	Leg Assembly as per	0.00 Dwg D3272.					- <del>- [</del>		12.05.15 -12.05.1
-			rivet out until weldin								1/12.51
		3-Bevel Aft e	end for welding		->						1.6 /000
		4-Inspect for	foreign object as per	QSI 024	•						
		5-Weld Aft E A/RAluminu	End Plate as per OSL om Rod // 9 7 8	004 & Dwg D3272						,	<b>4</b> 6.
		6-Grind End	Plate flush	? <b>~</b>						12	.05.16

7-Install last rivet as per Dwg.

	•									-
W/O:		······································	WO	RK ORDER CHANG	GES					
DATE	STEP	PRO	OCEDURE CHAI	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
,										
		+								
						· · · · · · · · · · · · · · · · · · ·				
					,					
				· .	, ,					
Part No		PAR #:	Fault Cate	gory:	NCF	R: Yes N	lo <b>DQ</b>	A:	_ Date: _	
	Re	esolution:	Disposition	n:	QA:	N/C Clo	sed:		Date: _	
NCR:		WORK ORDER NON-CONFORMANCE (NCR)  Corrective Action Section B						-		
DATE	STEP	Description of NC	<u> </u>	<u> </u>	tion B	0: 0	Verific	eation	Approval	Approval
DATE	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Secti	on C	Chief Eng	QC Inspector
***										
						~				
							ŀ			
-					,					
					,					
					1					
					t :					
•										f : :
					; F					

	Work Order ID 83727  April-24-12 1:24:10 PM		*83727*							Page 4		
Item ID: Revision ID:	D350-591-3	11		Accept	*N900	040	100	<b>)*</b> s	etup Star	1.71	S1*	
Item Name:	Heli-Access-S	tep, Long LH							Stop	*N	S2*	
Start Date: Required Date: Reference:	24/04/2012 08/05/2012	Start Qty: 10.00 Req'd Qty: 10.00	*10* *10*		Cust Item 1 Customer:	ID:						
Approvals:	Process Pla	n:	Date:	Tooling:	D	ate:	_	R	tun Star	*N	R1*	
• •			Date:	SPC (Y/N):	D	ate:			Stop	*N	R2*	
Sequence ID/ Work Center II	)	Operation Description QG10- Inspect visual per	OSI004- ground welds	Set Up/ Run Hours	Tool ID	Tool#	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp	
*100* QC Quality Control		Memo		0.00 571	5/17							
200		QC5- Inspect part comple	eteness to step on W/O	0.00								
*200* QC Quality Control		Мето		0.00	2/01/17							

210

Chemical Conversion Coat per QSI005 4.1

0.00

\*210\*
HandFinish

Memo

0.00

Hand Finishing

W/O:			V	<b>VORK ORDER CHANG</b>	ES					,
DATE	STEP	PROC	EDURE CH	IANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		L				1				
						r				
Part No	:	PAR #:	_ Fault Ca	tegory:	_ NCI	R: Yes	No DQA	:	Date:	
	R	esolution:	_ Disposit	ion:	_ QA	N/C CIG	osed:		Date: _	
NCR:		W	ORK OR	DER NON-CONFORMA	ANCE	(NCR	)			
DATE	STEP	Description of NC		Corrective Action Section	on B	Sign &			Approval	Approval
	U.L.	Section A	Initial Chief Eng	Action Description Chief Eng		Date	Verification Section C	n C	Chief Eng	QC Inspector
·					,					
					1			:		
										·
					1					
					,					
				·				<del></del>		
			·							
!					,			•		
			1	•	,	1	-			1

Work Ord April-24-12 1:2		727		*837	727*						Page 5
Item ID: Revision ID:	D350-591-3			Accept	*N900	040°	1 / O / ³	k Se	tup Sta Sto	I VI	S1*
Item Name:		Step, Long LH							310	<sup>ν</sup> *Ν	S2*
Start Date: Required Date:	24/04/2012 : 08/05/2012	Start Qty: 10.00 Req'd Qty: 10.00	*10* *10*		Cust Item II Customer:	D:					
Approvals:	Process Pla	an:	Date:	Tooling: _	Da	nte:		Ru		1/1	R1*
	QC:		Date:	<b>SPC (Y/N):</b>	Da	ite:			Sto	*N	R2*
Sequence ID/ Work Center II 220	D	Operation Description White Gloss(Ref:4.3.5.1)	per QSI005 4.3-Alum	Set Up/ Run Hours	Tool ID	Tool #		Accept Qty	Reject Qty	Reject Number	Insp. Stamp
*220* Powder Coating		Memo START TIM	E: 10 PERATURE: 22	0.00			1	υχ			12/25,
Ml2	1134	FINISH TIM	11-15	-							
230	·	Wing Walk as per dwg Q	SI005 4.4 Batch/2/56	<b>95</b> 0.00					1		4.4
*230* HandFinish Hand Finishing		Memo		0.00			<u> </u>	2	<b>\$</b>		BL 12-5-0
·											
* <b>2</b> 40		QC3- Inspect Part Finish		0.00			ij	io		برالم	1 12:05.22
OC		Mama		0.00			_	· <del></del>			1000

Quality Control

W/O:	İ		W	ORK ORDER CHANG	ES	1			•	•
DATE	STEP	PRO	CEDURE CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						,				
						'				
Part No	•	PAR #:	Fault Cat	egory:	_ NC	R: Yes 1	No <b>DQ</b>	A:	Date: _	
	R	esolution:	Dispositi	on:	_ QA	N/C Clo	sed:		Date: _	
NCR:		V	VORK ORI	DER NON-CONFORMA	NCE	(NCR)			······································	
DATE	STEP	Description of NC		Corrective Action Section	on B	Cian !	Verific		Approval	Approval
	U.L.	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Secti	on C	Chief Eng	QC Inspector
	 				r r					
					,					
										·
······································								<u> </u>		
					,		i .			
,					,					
					, ,	•		,		
					,					
		·			, ,					
						,				

<b>Work Orac</b> <i>April-24-12 1:2-</i>	er ID 83' 4:10 PM	727		*837	727*					Page 6	
Revision ID:	D350-591-31			Accept	*N900040	1100	)*	Setup	Start Stop	*NS1*	
	Heli-Access-St 24/04/2012 08/05/2012	Start Qty: 10.00 Req'd Qty: 10.00	*10* *10*		Cust Item ID: Customer:				Stop	*NS2*	
Approvals:		n:	Date:	Tooling: SPC (Y/N):	Date:		1	Run	Start Stop	*NR1* *NR2*	
Sequence ID/ Work Center II	)	Operation Description		Set Up/ Run Hours	Tool ID Tool ?	# Plan Code	Accept Qty	Rej Qty		Reject Insp. Number Stamp	
*250 *250* Packaging Packaging		Pick Kit  Memo	· · · · · · · · · · · · · · · · · · ·	0.00			/6x			125-	<del>)</del> 3.
260 *260* QC Quality Control		QC4- 100% Inspect kits for Memo	or completeness	0.00			16)			JM 13 0	B-2
270 *270* Packaging Packaging		Packaging  Memo	pack for shipping as per PP	0.00 0.00			10	<u> </u>		125	_3

Location:

Per D

Dail AC	ospace	LU								ŧ
W/O:			WC	RK ORDER CH	ANGES	,				•
DATE	STEP	PRO	OCEDURE CHAI	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						7				
Part No	):	PAR #:	Fault Cate	gory:	NC	R: Yes I	10 <b>DQ</b> /	A:	_ Date: _	
	R	esolution:	Disposition	1: <u></u>	QA	: N/C Clo	sed:		Date: _	
NCR:	NCR:		WORK ORD	ER NON-CONFO	DRMANCE	(NCR)				
DATE	STEP	Description of NC Section A	Initial	Corrective Action Action Descri	Section B ption	Sign &	Verific Secti		Approval Chief Eng	Approval QC Inspector
			Chief Eng	Chief Eng		Date				
-					, ,					
,					1 .					
					·					
					; ;					_
<u>.</u>		-			1					
					r r					
					1					
					,					

Work Ord		727		*837	727*						Page 7	-
Item ID: Revision ID: Item Name:	D350-591-3 Heli-Access-S			Accept	*N900	<b>040</b>	100	)* ፡	Setup Star	I A	S1* S2*	
Start Date: Required Date Reference:	24/04/2012	Start Qty: 10.00	*10* *10*		Cust Item I Customer:	D:				IN	.J/	
Approvals:	Process Pla	nn:	Date:	Tooling:	D:	ate:		ŀ	Run Stai Stoj	1/7	R1*	
	QC:		Date:	<b>SPC (Y/N):</b>	Da	ate:			Stop	′ *N	R2*	
Sequence ID/ Work Center	ID	Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp	-
<sup>280</sup> *280*		QC21- Final Inspection -	Work Order Release	0.00					12	15/	25 4	2
QC Quality Control		Memo	,	0.00					/	NCT 1	21051	23

Š

	bao												
W/O:			WORK ORDER CHANGES										
DATE	STEP	PRO	OCEDURE CHA	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
							·						
					:	r I							
Part No	:	PAR #:	Fault Category: NC				NCR: Yes No DQA: Date:						
	Resolution:		Disposition	on:	QA	N/C Clo	sed:		Date: _				
NCR:			WORK ORD	ER NON-CONFO	DRMANCE	(NCR	)						
DATE	STEP	Description of NC		Corrective Action	Section B	Cian 0	Verific		Approval	Approval			
DAIL	JILI	Section A	Initial Chief Eng	Action Descri	ption	Sign & Date	Secti	on C	Chief Eng	QC Inspector			
				•	1								
					ſ								
					t t	. · ·							
,					•								
					\$ r			•					
					1								
					1								
					1 r 1	, ,							
1	1	1	1 . 1			I /			1	i			

Picklist Print April-24-12 1:24:14	PM												Page
Work Order ID: 837	727		*5	33727	7*			<del></del>					
Parent Item: D3 Parent Item Name:	50-591-311 Heli-Access-Step, L	ong LH			-591-31	1*			art Date: 24/0 tart Qty: 10.0		-	l <b>Date:</b> 08/ d <b>Qty:</b> 10.	
Comments:	IPP Rev:A04.03.22 IPP Rev:B 07-06- IPP C returned to C by:EC IPP	09 Added D32	opter, r			v:EC							
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seg ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3272-1		Manufactured	No			110	Each	20.0000	1	10			
*D3272-1	*								**	A	e 12	1.05	· 02
•				Location	<u>on</u>	Loc	Oty	Loc Code					
				ST WA	B83731		-10 30		_	<u>(10)</u>	_		
					81312 81313		10 10		_		_	-	
<sup>D3067-1</sup>	*	Manufactured	No		61313	110	Each	187.0000	1 **	10	1		12)
End Plate											16/1	. 60 - 1	10

WA

WA016

81969\_\_\_

W/O:	···········		IANCES	<del> </del>								
	<u> </u>		V	VORK ORDER CH	IANGES	<u>;</u>		<del></del>	Approval			
DATE	STEP	PRO	OCEDURE CH	HANGE		Ву	Date	Qty	Chief Eng / Prod Mgr	Approval QC Inspector		
				,								
		· · · · · · · · · · · · · · · · · · ·		<u> </u>								
						,						
	<u> </u>				•							
						<u> </u>						
Part No	:	PAR #:							_ Date: _			
				Disposition: QA: N/C Closed: Date:								
NCR:			WORK OR	DER NON-CONF	ORMANC	E (NCR	)					
DATE	STEP	Description of NC Corrective Action			Section B		Verifica	tion	Approval	Approval		
DAIL	SILF	Section A	Initial Chief Eng	Action Descri	ption	Sign & Date	Section	1 C	Chief Eng	QC Inspector		
					,							
							}					
					<u> </u>		1					
					r r							
							:					
				1 1								
					,							
					,							
ı												

April-24-12 1:24:14 PM							-	Page 2
Work Order ID: 83727		*83	727*					The second secon
Parent Item: D350-591-311  Parent Item Name: Heli-Access-Ste	p, Long LH		350-591-31	1*		start Date: Start Qty:	24/04/2012 10.00	Required Date: 08/05/2012 Required Qty: 10.00
D3219-1 *D3219-1* Plate	Manufactured	No		110 E	ach 323.0000	) 2 <b>**</b>	20	12.05.10
			WA 82221 WA016  73410 77674 81292 82059 WA017	Loc Oty 84 84 118 12 6 80 20 121			20	- - - -  -
D3066-1 *D3066-1* Spacer	Manufactured	No	8[97]	121	ach 101.0000	) 2 <b>**</b>	30 38385	14 (9) Le 12.05.14
•			Location WA 81968	<u>Loc Qty</u> 101 101	Loc Code			- -
*M\$20600-AD4W4 *M\$20600-AD4V	Purchased	No	. <del>-</del>	180 E	ach 3,044.00	0 16 **	B1188	240 (160) Ac 12.05.1
			Location ST321 121011 121340 121444	Loc Oty 3044 9 1035 2000				- - - -

**Picklist Print** 

W/O:		WORK ORDER CHANGES											
DATE	STEP	PRO	CEDURE CHA	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
			•	•		,	·	.:					
						1		·					
					·	1							
Part No	:	PAR #:	Fault Cate	egory:	NCI	R: Yes	No <b>DQ</b>	٨:	_ Date: _				
	Re	esolution:	Disposition	on:	QA	N/C CI	osed:		Date: _				
NCR:	Resolution:		ORK ORD	ER NON-CONFORMA	NCE	(NCR	)		-				
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Section Action Description Chief Eng	n B	Sign & Date	Verification Section C		Approval Chief Eng	Approval QC Inspector			
		:	O.M.O. E.N.G		:								
•				•									
				· .									
									•				
			·		,								
		·			. ·	·							
		·							·				
					,				,				

April-24-12 1:24:14 PM						•		Page 3
Work Order ID: 83727		*83	3727*					<del></del>
Parent Item: D350-591-311 Parent Item Name: Heli-Access-S	tep, Long LH		350-591-3	311*		Start Date:		Required Date: 08/05/2012 Required Qty: 10.00
D3065-041  *D3065-041*  Step Leg Assembly Hi	Manufactured	No	<u>Location</u> WA	180 I <u>Loc Otv</u>	Each 19.0000  Loc Cod	**	10 <u>B 833</u>	68 (B) Ae 12.05-17
<sup>D3067-1</sup> *D3067-1*	Manufactured	No	66149 78798 79336	( 18	) 3	00 I **	10	1. 12.06.15
End Plate			Location  WA  78608 80881 81969  WA016  67582 68214 79607 83053	Loc Oty 123 4 45 74 64	4 5 4 4 2 8	<u>e</u>	/0	
*AN3-35A*  *Bolt	Purchased	No	Location ST353 120644 120717 121068		Each 147.000  Loc Cod  7	**	20 	p 12-5-23.

W/O:				<i>*</i>						
DATE	STEP	PRO	CEDURE CH	IANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
-			<del></del>				·			
										,
					, F					
Part No		PAR #:	Fault Ca	tegory:	_ NCF	R: Yes	No DQA	<b>\</b> :	_ Date: _	
	R	esolution:	Disposit	ion:	_ QA:	N/C CI	osed:		Date: _	· · · · · · · · · · · · · · · · · · ·
NCR:			WORK OR	DER NON-CONFORM	ANCE	(NCR	)			
DATE	STEP	Description of NC	And the last		ion B	Sign &	Verification			Approval
	0.2.	Section A	Initial Chief Eng	Action Description Chief Eng		Date	Section	on C	Chief Eng	QC Inspector
					,			-		
		<u> </u>								·
•					;			-		,
		·			•					
					,					
					' .					

April-24-12 1:24:14 PM

**Shop Packet Print** 

\*\*

Page 4

						<del></del>				<del></del>			
W/O:			WORK ORDER CHANGES										
DATE	STEP	PRO	OCEDURE CH	IANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
			•										
			•			,							
						r			'				
Part No	•	PAR #:	Fault Ca	tegory:	NC	R: Yes	No DQA			· · · · · · · · · · · · · · · · · · ·			
				Disposition: QA: N/C Closed:									
NCR:			WORK OR	DER NON-CON	FORMANC	E (NCR	R)						
DATE	STEP	Description of NC		Corrective Action		O: 0	Verifica		Approval	Approval			
DAIL	JILI	Section A	Initial Chief Eng	Action Des		Sign & Date	Section	n C	Chief Eng	QC Inspector			
		,											
					,					•			
					1								
					· · · · · · · · · · · · · · · · · · ·								
					<del> </del>								
					· :				-				
					,								
Í	1				:	į	- 1		l				

#### **Picklist Print** Page 5 April-24-12 1:24:14 PM Work Order ID: 83727 \*83727\* \*D350-591-311\* Parent Item: D350-591-311 Parent Item Name: Heli-Access-Step, Long LH **Start Date: 24/04/2012 Required Date:** 08/05/2012 **Start Qty: 10.00** Required Qty: 10.00 Purchased No 250 Each 186.0000 Location Loc Oty Loc Code 340 100 121181. 100 ST340 86 120187 36 120731 50 Manufactured No 250 220.0000 20 Each \*\* Location Loc Qty Loc Code ST012 220 76130 2

(D2230-3) \*D2230-3\*

 Location
 Loc Qty

 ST480
 147

 53881
 4

 70973
 1

 81558
 142

250

78537

80474

Manufactured

No

Loc Code

147.0000


18 200

Each

\_\_\_\_\_\_

April-24-12 1:24:14 PM

W/O:		WORK ORDER CHANGES											
DATE	STEP	PRO	OCEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
						<del></del>							
					.								
		-						·					
Part No	:	PAR #:	Fault Cat	egory:	NCR: Yes	No DQ	\:	Date: _					
			Disposition: QA: N/C Closed: Date: _										
NCR:		9	WORK OR	DER NON-CONFORMA	NCE (NCF	R)							
DATE	STEP	Description of NC	1	Corrective Action Section	on B Sign &	Verific			Approval				
	O.L.	Section A	Initial Chief Eng	Action Description Chief Eng	Date		on C	Chief Eng	QC Inspector				
									,				
<u>-</u>													
				·									
		,											
		,				1							




Dart	<b>Aeros</b>	pace	Ltd
------	--------------	------	-----

W/O:	3	WORK ORDER CHANGES												
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector					
ŀ														
					;									
					NCR: Yes No DQA: Date:									
Res		esolution:	Disposition	l:	QA: N/C C	osed:		Date: _	· <del>- · · · · · · · · · · · · · · · · · ·</del>					
NCR:			WORK ORDE	R NON-CONFORMAN	ICE (NCF	₹)		?	र्द					
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Section Action Description Chief Eng	Sign & Date			Approval Chief Eng	Approval QC Inspector					
-														
		_												
							•							

Dun Avi	Johaso					,				( €, <b>*</b> ∂
W/O:			WO	RK ORDER CHANGE	ES					•
DATE	STEP	PRO	OCEDURE CHAI	IGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
					!		,			, ·
Part No	·	PAR #:	Fault Categ	jory:	NCF	: Yes N	o <b>DQ</b>	٨:	_ Date: _	
	Re	esolution:	Disposition	l:	QA:	N/C Clos	sed:	·	Date: _	
NCR:		,	WORK ORDE	R NON-CONFORMA	NCE	(NCR)				
DATE	STEP	Description of NC		Corrective Action Section	n B		Verific	ation	Approval	Approval
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	1	Sign & Date	Section		Chief Eng	QC inspector
					;					
·					,			<del>.</del>		·
		·								
		i			,					
		· · · · · · · · · · · · · · · · · · ·			,					
								,		



	DESIG	P	DRAWN BY	DART AEROSPACE HAWKESBURY, ONTARIO, CANAD	
	CHECK	SED.	APPROVED	DRAWING NO.	REV. B
		E	世	D3272	SHEET 1 OF 3
ı	DATE		<u>-</u>	TITLE	SCALE
	07.0	5.18		STEP ASSEMBLY, HI LONG	NTS
	Α		04.03.01	NEW ISSUE	
	В		07.05.18	D3272-1 WAS D2622-120	



QTY -041	QTY -042	PART NUMBER	DESCRIPTION
X		D3272-041	STEP ASSEMBLY, HIGH LONG (LH)
	Х	D3272-042	STEP ASSEMBLY, HIGH LONG (RH)
1	1	D3065-041	LEG ASSEMBLY
2	2	D3066-1	SPACER
2	2	D3067-1	END PLATE
2	2	D3219-1	SUPPORT
1	1	D3272-1	STEP
*			
16	16	MS20600AD4W4	RIVET

#### **GENERAL NOTES:**

- 1) D3272-041 SHOWN. FOR D3272-042, INSTALL D3219-1 SUPPORT OPPOSITE SIDE
- 2) WELD PER DART QSI 004
- 3) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005.4.1 POWDER COAT ASSEMBLY WHITE (4.3.5.1) PER DART QSI 005 4.3 BLACK ANTI-SKID PAINT PER DART QSI 005 4.4
- 4) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED.
- ALL DIMENSIONS ARE IN INCHES UNLESS OTHERWISE NOTED.
- BREAK ALL SHARP EDGES 0.005 TO 0.010 MAX.


JNCONTROLLED COPY

Copyright © 2004 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Dart	<b>Aeros</b>	pace	Ltd


	•								
W/O:		<del></del>	WC	RK ORDER CHANG	ES				
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	No <b>DQ</b>	A:	Date:	
		esolution:							
NCR:	·		WORK ORDI	ER NON-CONFORMA	NCE (NCR	)			
DATE	STEP	Description of NC		Corrective Action Section		Verific	cation	Approval	Approval
DAIL	JILI	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Sect	ion °C	Chief Eng	QC Inspector
									:
					·				
	}								





Dart Aerospace	Ltd
----------------	-----

	Johnson									<b>€</b> •\$•
W/O:			W	ORK ORDER CHANGE	S	· · · · · · · · · · · · · · · · · · ·				. •
DATE	STEP	PRO	OCEDURE CHA	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No		PAR #:	Fault Cate	egory:	NCF	R: Yes	No DQ	A:	Date:	
	R	esolution:	Disposition	on:	QA:	N/C Clo	sed:		Date:	
NCR:			WORK ORD	ER NON-CONFORMAN	ICE	(NCR	)			
DATE	STEP	Description of NC		Corrective Action Section	В		Verific	ation	Approval	Approval
	JILF	Section A	Initial Chief Eng	Action Description  Chief Eng		Sign & Date	Secti	on C	Chief Eng	QC Inspector
					,			·		
•										
										·
ı					,					
								,		
					r .					









Copyright © 2004 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Dart Ae	rospace	e Ltd					E .			- CC-20
W/O:				WC	ORK ORDER CH	IANGES	1			•
DATE	STEP		PRO	CEDURE CHA	NGE		Ву	Date (	Appro Chief E Prod	ing / Approva
							,			
		_								
				·		····				
Part No	o:		PAR #:	Fault Cate	gory:	NC	R: Yes	No <b>DQA</b> :	Da	te:
	R	esolutior	n:	Disposition	n:	QA	: N/C CI	osed:	Da	te:
NCR:			W	ORK ORDI	ER NON-CONFO	DRMANCI	E (NCF	R)		
DATE	STEP		Description of NC		Corrective Action	Section B	T	- Verificati	on Appre	oval Approva
DATE	SIEP		Section A	Initial Chief Eng	Action Descrip	ption 	Sign 8 Date	Section (		
		}	+ 2,							
,						, , !				
						r t				
						7				
	1	I		1 1			1		1	

# DART AEROSPACE LTD. JOHN STAND

D350-591 Page 23 of 23

Qty -211	Qty -212	Qty -213	Qty -214	Qty -215	Qty -216	Qty  -311	Qty -312	Part Number	Description
Х		<u> </u>				-3		D350-591-211	Heli-Access-Step™, Long Step - High Skid, LH
	X							D350-591-212	Heli-Access-Step™, Long Step - High Skid, RH
		Х						D350-591-213	Heli-Access-Step™, Short Step - High Skid, LH
			Х			†		D350-591-214	Heli-Access-Step™, Short Step - High Skid, RH
				X	<del></del>			D350-591-215	Heli-Access-Step™, Short Step – Low Skid, LH
		<del></del>			X			D350-591-216	Heli-Access-Step™, Short Step - Low Skid, RH
		<del> </del>		· ·		X		D350-591-311	Heli-Access-Step™, Long Step - High Skid, LH
						<del> </del>	Х	D350-591-312	Heli-Access-Step™, Long Step – High Skid, RH
1								D3070-041	STEP ASSEMBLY (HIGH-LONG, LH)
	1							D3070-042	STEP ASSEMBLY (HIGH-LONG, RH)
		1						D3078-041	STEP ASSEMBLY (HIGH-SHORT, LH)
			1					D3078-042	STEP ASSEMBLY (HIGH-SHORT, RH)
				1				D3168-041	STEP ASSEMBLY (LOW-SHORT, LH)
					1			D3168-042	STEP ASSEMBLY (LOW-SHORT, RH)
						1		1D3272-041	STEP ASSEMBLY (HIGH-LONG, LH)
						1	1	D3272-042	STEP ASSEMBLY (HIGH-LONG, RH)
4	4							D2182B035	RUBBER CUSHION
		2	2	2	2	1		D2230-1	MOUNTING LUG
		2	2	2	2 1	4 1	4	D2230-3	MOUNTING LUG 1
8	8							D2274	RADIUS BLOCK
						2	2	D2618	BUSHING I
4	4	4	4	4	4			D2732-030	CUSHION
2	2	1	1	1	1 1	2	2	D2856-400-720	ABRASION STRIP!
2	2							D3064-1	CLAMP
1	1							D3079-041	SUPPORT ASSEMBLY
4	4					1		_D3080-1	CLAMP
					,	2. 2.2 ast	2	D3235-1	MOUNTING LUG
						1	1	\D3278-041	SUPPORT ASSEMBLY
					-			110 054	DOLT!
2	2	2	2	2	2	2	2	AN3-35A	BOLT
10	10	2	2	2	2	<b> </b>		AN4-11A	BOLT
		4	4	4	4	8	8	, AN4-13A	BOLTI
		ļ		ļ	1	2	2	*AN5-36A	BOLT
4	4	4	4	4	4	4	4	I AN960JD10	WASHERI
20	20	12	12	12	12	تم 16 س	, 16	AN960JD416	WASHER!
						<u> </u>	4	, AN960JD516	WASHER!
2	2	2	2	2	2	2	2	MS21042L3	NUT I
10	10	6	6	6	6	8	8	MS21042L4	NUT I
						2 2	. 2	"MS21042L5	NUT
				1		1 1	1	*DSI 9410-011	STEP MODIFICATION KIT

\*DSI 9410-011 Step Modification Kits are provided with all D350-591-311 and D350-591-312 Steps. This kit is provided as an option for the installer and is therefore **NOT REQUIRED** to complete the installation of the D350-591-311 or D350-591-312 Steps. Refer to Figure 21 for installation of the DSI 9410-011 Kit.

• COPYRIGHT @ 1993 BY DART AEROSPACE LTD •
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Revision: **G** 

Date: 08.10.06

# \*83727\*

April-24-12 1:24:10 PM

Item ID:

D350-591-311

Accept

\*N900040100\*

Setup Start \*NS1\*

**Revision ID:** 

Start Date:

Item Name:

Heli-Acalss-Step, Long LH

Start Qty: 10.00 24/04/2012

Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan: MLJ

Req'd Qty: 10.00

Date: \Z/U4/Z4Tooling:

Date:

Run

Required Date: 08/05/2012

Date:

SPC (Y/N):

Date:

Stop

QC:

Operation

Set Up/

Tool ID

Tool # Plan Accept

Reject

Reject

Sequence ID/

Description

**Run Hours** 

Qty Code

**Qty** 

Insp. Number Stamp

Work Center ID Draw Nbr

**Revision Nbr** 

D3272

Rev B

\*100\* DC

100

Document Control

DOCUMENT CONTROL

Memo

Photocopy bluefile and type labels as per PPP D350-591-311 CHG001

0.00

0.00

110

\*110\*

Large Fab

0.00

0.00

Large Fab Large Fab

Memo

1-Bevel end for welding FWD ONLY

2-Weld Support using Jig DT8719, weld Fwd End Plate as per QSI 004 & Dwg

A/RAluminum Rod M 119785 3-Grind End Plate flush